

- Factors: \downarrow cutting speed
- \rightarrow ~~rough~~ ~~cut~~ ~~type~~ \rightarrow coarse feed
 - \rightarrow \downarrow rake angle \rightarrow Insufficient cutting fluid
 - \rightarrow Large uncut thickness
 - \rightarrow Strong adhesion bet. chips & tool face.

Chip breakers:

- \rightarrow Long and cont. chip formation ^{@ \uparrow cutting speed} affects m/c'ing.
- \rightarrow Spoils tool, work & m/c.
- \rightarrow Chips - hard sharp & hot.
- \rightarrow Dangerous & difficult to remove
- \rightarrow Chip breakers help easy removal, provides

safety and preventing damage

- \rightarrow Used in automated machines running @

\uparrow speeds.

- (1) Step type (2) Groove type (3) Clamp type



5) Cutting Tool Materials:

\rightarrow Tool - harder than material to be cut

Parameters - Tool matn. selection:

1. Volume of production
2. Tool design
3. Types of m/c'ing process
4. Physical & chem. properties of work material
5. Rigidity & cond. of m/c.

Properties:

1. Hot hardness
2. Wear resistance

- Types: -
1. Carbon tool steel
 2. High speed steel
 3. Cemented Carbides
 4. Ceramics
 5. Diamonds.

1. Carbon Tool Steel:

C - 0.8 to 1.3% | Si - 0.1 to 0.4% | Mn - 0.1 to 0.4%

- \rightarrow \downarrow cutting speeds, temp: $< 200^\circ\text{C}$.
- \rightarrow \uparrow Hardness, strength & toughness
- \rightarrow Good temp. tolerance.
- \rightarrow Blades, hack saw blades, taps, etc.

→ Med. Alloy tools: W, Mo, Cr & Vd.
→ 5% C + Cr + Mo - ↑ Hardness

2. High speed Steels:

- Effective even on ↑ speeds.
- Superior hot hardness, ↑ wear resistance
- Maintain hardness upto 900°C.

→ ~~243~~ ↑ ^{Cutting} speeds than Carbon Steel.
Eg: Tungsten, Cr, Vd, Co & Mo

Types of HSS:

(i) 18-4-1 High speed Steel:

* 18% - W, 4% - Cr, 1% - Vd
0.5% - C

* Great performance

* Hardness maintained upto 600°C

(ii) Mo HSS:

* 6% - Mo, 5% - W, 4% - Cr, 2% - Vd
* Tough

(iii) Cobalt HSS:

* 12% - Co, W - 20%, Cr - 4%, Vd - 2%

* Heavy duty & rough cutting tool

* Used in Milling cutter, Lathe tool

3. Cemented Carbide:

→ Mixture of Tungsten powder & Carbon
@ 1500°C, 4:6 ratio.

→ 82% - WC, 10% - TiC & 8% - Co & it

is usually taken from inserts (either brazed or clamped)

→ These clamps are thrown after wear
out all cutting edges and this tool withstands
temp. upto 1000°C.

→ 6 times speed than HSS.

→ Brittle & low resistance to shock.

4. Ceramics:

→ Misco. of Al_2O_3 & BN & sintered @ $1700^\circ C$
which has very hard & good compressive strength.

→ Brittle, can't be used in shock & vibrations

→ 90% Al_2O_3 + 10% CrO_2 , MnO_2 & NO_2

→ High compressive strength, longer tool life,
flexibility, good surface finish & high temp. resistance $1000^\circ C$

Prop.: * \uparrow cutting speeds

* Rigidity of tool & w/p

* \uparrow surface finish on cutting tool

* Eliminates unbalanced forces.

5. Diamonds:

→ Hardest cutting materials.

→ Polycryst. made by sintering under

high pressure & temp.

→ Has low coeff. of friction, comp. strength \uparrow &

wear resistance.

→ Used for machining very hard materials

like glass, plastics, ceramics, etc.

→ \uparrow surface finish @ \uparrow speeds & good
dimensional accuracy.

→ Very expensive & brittle


Prop.: * Hardest sub.

* \downarrow coeff. of friction

* \uparrow Heat cond.

* \downarrow elec. cond.

Tool Wear:



Flank wear: → edge wear aka Flank wear

→ Friction, abrasion & adhesions - main cause

→ Flat worn out region behind cutting edge.

→ Takes place in rough machined surface